

P1000 reference

1	thousand	1000μl
0	hundred	
0	tens	

- **First stop/ Soft stop:** used for measuring the volume.
Press the plunger until you feel resistance.
- **Second stop/ hard stop:** Used to completely eject the measured liquid.
Press the plunger past the first stop.
- Use a new **tip** every time!

